## **DMR Copy of Record**

Permit													1							
Permit #:		MAR053712			Permittee:			ReEnergy Holdings					Facility: REEN				ENERGY ROXBURY, INC.			
Major:		No			Permittee Address:			101 Gerard Street Roxbury, MA 02119					Facility	101 GERARD STREET ROXBURY, MA 02119						
Permitted Feature:	ermitted Feature: 001 External Outfall				Discharge:			001-UK Copper: Wate												
Report Dates & Sta	ntus																			
Monitoring Period: From 07/01/20 to 09/30/20					MR Due Date	:		11/30/20					Status: NetDMR Validate					lidated		
Considerations for	·																			
Principal Executive	e Officer																			
First Name:					itle:								Telephone:							
Last Name:																				
No Data Indicator (NODI)																				
Form NODI:																				
Paramete	er	Monitoring Locat	ion Season#	Param. NOD	)I		Quantit	ty or Loading			(	Quality or	Concentrat	ion		# o	of Ex.	Frequency of	of Analys	sis Sample Type
Code	Name					ualifier 1	Value 1	Qualifier 2 Value	e 2 Units Qualifi	ier 1 Va	ue 1 Quali	fier 2 Valu				its		24/00 0	d a ale c	OD ODAD
V	4-4-1 [ C	4 F#lant Cra.			Sample Permit Req.								= <=	64.0 33.2 MAX	28 - IMUM 28 -			01/90 - Quarl 01/90 - Quarl	-	GR - GRAB GR - GRAB
X 01042 Copper,	total [as C	[u] 1 - Effluent Gros	SS U		Value NODI											1			,	
Submission Note																				
If a parameter row d	oes not co	ontain any values fo	r the Sample	e nor Efflue	ant Trading the	an none	of the	following fields	e will he suhm	nittad fo	or that row	w: I Inite I	Number o	f Eveursion	e Fregue	ncy of	Anal	veie and 9	Sample	Type
Edit Check Errors	003 1101 00	oritain arry values re	i inc campi	C HOI EIIIGC	in mading, the		or the	Tollowing ficial	3 WIII DC SUDII	iiiiiou io	n that lov	w. Orinto, i	Number 0	LXCUISION	o, i reque	illey of	Allai	yoio, and c	Dampic	турс.
Luit Check Liftors																				
Parameter		Monitoring		Field		Туре		Description										Acknowledge		
Code Name		Location				.,,,,,				p.io										
01042 Copper, total Cu]	[as 1	- Effluent Gross	Quality or Co 3	oncentration	tion Sample Value Soft The			provided sample value is outside the permit limit. Please verify that the value you have provided is correct. (Error Code: 1											ode: 1	Yes
Comments																				
Copper exceeded th	e benchm	nark of 33.2 ug/L. Th	ne Facility co	ontinues to	use BMPs suc	h as str	reet swe	eeping, silt sad	cks in catch b	asins a	nd hay b	ales. Nev	v controls	will continu	ie to be e	xplored	d.			
Attachments								, 0.								•				
No attachments.																				
Report Last Saved	By																			
ReEnergy Holdings	S																			
User:		U																		
Name: Frederic Bruneau					u															
E-Mail: fbruneau@reenerg					oldings.com															
Date/Time: 2020-11-24 16:40					ime Zone: -05	:00)														
Report Last Signed	d By																			
User: FBRUNEAU				U																
Name: Frederic Bruneau				Bruneau																
E-Mail: fbruneau@reenerg				reenergyho	oldings.com															
Date/Time:					ime Zone: -05	:00)														